


Redukcje



VRS

zł cze e skie do w a



Zł cze	Al	Ms	St
VRS5032	+	+	+
VRS5038	+	+	+
VRS50	+	+	+
VRS3832	+	+	+
VRS3838	+	+	+



VRSZ

zł cze m skie do w a



VRSZ5032	+	+	+
VRSZ5038	+	+	+
VRSZ50	+	+	+
VRSZ75	+	+	+
VRSZ100	+	+	+



RS

redukcja gwint zewn trzny-> gwint wewn trzny

RS2025	+	+	+
RS2030	+	+	+
RS3020	+	+	+
RS3040	+	+	+



DN

zł cze gwint zewn trzny-> gwint zewn trzny

DN20	+	+	+
DN30	+	+	+



RN

redukcja gwint zewn trzny-> gwint zewn trzny

RN2520	+	+	+
RN2030	+	+	+
RN3020	+	+	+
RN3040	+	+	+